

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Casey, William**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-026712**Date Inspected:** 16-Nov-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 730**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1600**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Job Site**CWI Name:** William Norris**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** S.A.S. components**Summary of Items Observed:**

The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI reviewed contract documents at pier 7. The QAI used approved weekly welding report submittals and cross referenced the welding and inspection status as reported with QA records to identify the overall weld status. The QAI continued reviewing welding report packages 87, 88 and 89 for conformance with the contractor requirements. The QAI was provided with the informal weekly welding report package #90 and began a cursory review of the inspection reports. The QAI continued reviewing documents and compiling the weld status from submittal documentation. The QAI finished reviewing packages 87 and 88, and noted that there are several reports that appear to need corrections of the weld locations and other reports that are missing the inspector's signature. The QAI relayed these comments to the QAI lead Bill Levell. The QAI also met with the Quality Control Inspector (QCI) William Norris and reviewed the observations from these report reviews.

Summary of Conversations:

The QAI relayed the status of the document reviews to the QAI Lead Bill Levell. Except as described above, there were no other notable conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy (510) 385-5910, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By: Croff,Scott

Quality Assurance Inspector

Reviewed By: Levell,Bill

QA Reviewer